


Product Obsolescence Memo

INDUCTIVE COMPONENTS



May, 2013

Various Transformers to be Discontinued

Bourns will be discontinuing the various transformers listed below. A lack of sales volume and diminishing demand necessitates this action.

Obsolete Part Numbers:

PT10314L	PT51250L	PT61008EL	PT66003L	PT74263NL	SM51522L
PT23101L	PT51326L	PT61008L	PT66004EL	PT74344EL	SM51523EL
PT23102L	PT60004L	PT61010EL	PT66004L	PT74344L	SM51523L
PT23103L	PT60005L	PT61010L	PT66005EL	PT75426EL	SM51524EL
PT23104L	PT61002EL	PT61011EL	PT66005L	PT75426L	SM51524L
PT23105L	PT61002L	PT61011L	PT66006EL	SM51150EL	SM51593EL
PT23301L	PT61003EL	PT61023EL	PT66006L	SM51285EL	SM536-1EL
PT23302L	PT61003L	PT61023L	PT66011AL	SM51286EL	SM536-1L
PT23303L	PT61004EL	PT61024EL	PT66012EL	SM51507EL	SM74346EL
PT23321L	PT61004L	PT61024L	PT66012L	SM51508EL	SM74346L
PT23401L	PT61005EL	PT66001EL	PT71949L	SM51510EL	SM75225EL
PT23402L	PT61005L	PT66001L	PT73031L	SM51521EL	SM75225L
PT23403L	PT61006L	PT66002EL	PT73173L	SM51521ELM	SM75719EL
PT23404L	PT61007EL	PT66002L	PT73434L	SM51521ELP	SM75719L
PT31407L	PT61007L	PT66003EL	PT73455L	SM51522EL	

Please plan for the following deadlines:

Last Time Buy Date: November 30, 2013

Last Time Ship Date: May 31, 2014

We regret that there are no suitable replacement parts at this time.

Should you have any questions or need additional information, please feel free to contact [Customer Service/ Inside Sales](#).