



Carton Box Change for Various Sensors and Controls

Riverside, California – June 22, 2022 – In the spirit of continuous improvement, effective immediately, Bourns will change the design of the carton box used for various [Sensors and Controls](#). As depicted below, this change will reduce the gap between the inner boxes and carton, thereby decreasing the available space for the boxes to shake in the carton during transportation.

The minimum order quantity and order multiple will remain unchanged. A list of affected model series and part numbers is included below.

Old Carton Box

Carton size: 55 x 29 x 23 cm

Gap of height between inner box and carton: 2 cm



Gap of length between inner box and carton: 1 cm



New Carton Box

Carton size: 54 x 29 x 21.5 cm

Gap of height between inner box and carton: 0.5 cm



Gap of length between inner box and carton: None



SC2209

Affected Part Numbers

PDB12-JAB01-103BF	PDB12-F2
PDB12-F4	PDB241-E420
PDB12-G2	PDB241-E425
PDB12-G4	PDB241-E430
PDB12-H2	PDB241-S420
PDB12-H4	PDB241-S425
PDB12-H4201-254BF	PDB241-S430
PDB12-H4201-254BF	PDB241-D420
PDB12-M2	PDB241-D425
PDB12-M4	PDB241-D430
PDB183-K	PDB241-E415P-105A1
PDB183-S	PDB241-EVH01-254A1
PDB183-S	PDB241-EVH01-504A1
PDB183-GTR01/GTR02/GTR03	PDB241-EVH02-254A1
PDB183-GTR05	PDB241-EVH02-504A1
PDB183-GTR11	PDB241-EVH03-254A1
PDB183-GTR13	PDB241-EVH04-504A1
PDB183-GTR21/GTR22	PDB241-ESP01-254A2
PDB183-GTR31	PDB241-ESP01-504A2
PDB183-GTR32	PDB241-ESP01-504B0
PDB183-FSH04-253A3	PDB241-ESP01-254B0
PDB183-FSH05-253A3	PDB241-FDR01-254B0
PDB183-FSH06-253A3	PDB241-FDR02-254B0
PDB183-FSH07-253A3	PDB241-FSH01-253A3
PDB183-WDM17-254A2	PDB241-FSH02-253A3
PDB183-WDM18-504A2	PDB241-FSH03-253A3
PDB183-WDM19-254A2	PDB241-GTR01/GTR02
PDB183-WDM20-504A2	PDB241-GTR03/GTR04
PDB183-TSR01-504A2	PDB241-GNL01/GNL02
PDB183-MTX01-254A2	PDB241-GNL03
PDB183-MTX01-504A2	PDB241-GNL04
PDB241-E220	PDB241-GNL11
PDB241-E225	PDB241-GNL13
PDB241-E230	PDB241-WDM13-254B0
PDB241-S220	PDB241-WDM14-504B0
PDB241-S225	PDB241-WDM15-254B0
PDB241-S230	PDB241-WDM16-504A2
PDB241-D220	PDB241-SYD02
PDB241-D225	PDB241-SYD03
PDB241-D230	PDB242-D420K

Affected Part Numbers (continued)	
PDB242-D425K	PTA4543-22
PDB242-D425P	PTA4544-20
PDB242-D430K	PTA4544-22
PDB242-E420K	PTA4553-20
PDB242-E425K	PTA4553-22
PDB242-E430K	PTA4554
PDB242-E430P	PTA45A3-20
PDB242-S420K	PTA45A3-22
PDB242-S425K	PTA6043-20
PDB242-S430K	PTA6043-22
PTA0143-2010CIB103	PTA6044-20
PTA1543-20	PTA6044-22
PTA1543-22	PTA6053-20
PTA1544-20	PTA6053-22
PTA1544-22	PTA6054-20
PTA2043-20	PTA6054-22
PTA2043-22	PTB0143
PTA2044	PTB0144
PTA2053-20	PTB0153
PTA2053-22	PTB0154
PTA2054	PTB4543
PTA3043-20	PTB4544
PTA3043-22	PTB4553
PTA3044	PTB4554
PTA3053-20	PTB6043
PTA3053-22	PTB6044
PTA3054	PTB6053
PTA4543-20	PTB6054

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).