




PRODUCT OBSOLESCENCE MEMO

MAGNETICS



Bourns® Model RLH9012-151KL, RLH9012-331KL, and RLH9012-390KL Radial Inductors to be Discontinued

Riverside, California – October 10, 2022 - In accordance with our ongoing product life cycle management procedure, Bourns will transfer the Model RLH9012-151KL, RLH9012-331KL and RLH9012-390KL Radial Inductors to an End of Product Life status. A lack of sales volume and diminishing demand necessitates this action.

The [Model RLB9012 Series Radial Inductors](#) are the recommended replacement. The form, fit and function of the suggested replacement parts are not identical to the obsolete parts. However, the specifications of the suggested replacement Model RLB9012 Series are likely to be substitutable in typical applications. Please refer to Bourns' data sheets for more information. The discontinued part numbers and their recommended replacement part numbers can be found in the table below.

Affected Part Numbers:

Obsolete Part Number	Replacement Part Number
RLH9012-151KL	RLB9012-151KL
RLH9012-331KL	RLB9012-331KL
RLH9012-390KL	RLB9012-390KL

Customers must notify Bourns in writing within 30 days of publication of this notification if they consider the discontinued part numbers to be sole sourced by Bourns. In such cases, Bourns will work with customers to negotiate an appropriate End of Product Life purchase for the discontinued products. Orders for these discontinued products during this End of Product Life transition period will be considered non-cancellable. Products purchased during this End of Product Life transition period will be considered non-returnable and will be covered by Bourns' standard warranty.

Please plan for the following deadlines:

Last time buy date: **December 19, 2022**

Last time ship date: **March 19, 2023**

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

IC22118