

Product Obsolescence Memo

INDUCTIVE COMPONENTS



April, 2016

Bourns® Model 5600 Series High Current Chokes to be Discontinued

Bourns has decided to discontinue the [Model 5600 Series High Current Chokes](#). A lack of sales volume and diminishing demand necessitates this action.

Bourns does not offer direct replacement options for the Model 5600 Series. However, customers may find the [Model 1130](#) and [1140 Series](#) High Current Chokes as suitable replacement options. Please contact the Bourns team of Field Application Engineers if you have any questions regarding the suggested replacement parts and your application requirements.

Obsolete part numbers:

5601-RC	5609-RC	5617-RC	5625-RC
5602-RC	5610-RC	5618-RC	5626-RC
5603-RC	5611-RC	5619-RC	5627-RC
5604-RC	5612-RC	5620-RC	5628-RC
5605-RC	5613-RC	5621-RC	5629-RC
5606-RC	5614-RC	5622-RC	5630-RC
5607-RC	5615-RC	5623-RC	5631-RC
5608-RC	5616-RC	5624-RC	5632-RC

Please plan for the following deadlines:

*Last time buy date: **October 8, 2016***

*Last time ship date: **April 8, 2017***

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).