



1655 Scott Boulevard  
Santa Clara, California 95050-4169  
United States Country Code (1)  
(408) 985-2400  
FAX No. (408) 296-3256  
<http://www.ul.com>

E174545, 00SC13970

August 31, 2000

Bourns Multifuse  
c/o Bourns Multifuse (Taiwan) Ltd.  
Lin-Kou Taipei Hsien

Fax No: 011-886-2-2603-2602

Attention: Mr. Leo Liu

Reference: File E174545, Project No. 00SC13970

Subject: PTC Thermistor, Model MF-ESMD190

Dear Mr. Liu:

NOTICE OF AUTHORIZATION TO APPLY THE UL MARK

UL's investigation of your product has been completed under project number 00SC13970 and the product was determined to comply with the applicable requirements.

This fax temporarily supplements the UL Follow-Up Services Inspection Procedure and serves as authorization to apply the UL Listing Mark only at the factory under UL's Follow-Up Service Program to the above product which is constructed as described below:

Modified as Follow:

1. Model Designation MF-MSME190 changed to MF-ESMD190

To provide the manufacturer with the intended authorization to use the UL Mark, the addressee must send a copy of this Notice and all attached material to each manufacturing location as currently authorized in File E174545, Vol. 1. Sec. 8.

This authorization is effective for 90 days from the date of this Notice and only for products at the indicated manufacturing locations. Records in the Follow-Up Services Procedure covering the product are now being prepared and will be sent to the indicated manufacturing locations in the near future. Please note that the Follow-Up Services Procedures are sent to the manufacturers only unless the Applicant specifically requests this document.


A not-for-profit organization  
dedicated to public safety and  
committed to quality service

E174545, 00SC13970  
August 31, 2000  
Page 2

Products which bear the UL Mark shall be identical to those which were evaluated by UL and found to comply with UL's requirements.


If changes in construction are discovered, authorization to use the UL Mark may be withdrawn and products that bear the UL Mark may have to be revised (in the field or at the manufacturer's facility) to bring them into compliance with UL's requirements.

Regards,



STEVEN WEISS (Ext. 31943)  
Associate Project Engineer  
Engineering Services  
Section 3016K  
Email: Steven.Weiss@us.ul.com

Reviewed by:



MARGARET KIEFER  
Senior Project Engineer  
Engineering Services  
Section 3016K

cc: Attention: Mr. Steve Turner  
Bourns Multifuse  
Riverside, CA  
Fax No: 909-781-5555