



Underwriters Laboratories Inc.®

1885 Scott Boulevard  
Santa Clara, California 95050-4169  
(408) 985-2400  
FAX No. (408) 295-3256  
Circle ULINC SANTA CLARA, CA

E174545, 98SC2224

March 20, 1998

Bourns Multifuse  
Riverside, CA

Fax No: 1-909-781-5555

Attention: Mr. Jason Moulton

Subject: MF-MSM020, -MSMC035, -MSMC050, -MSM050, -MSMC075,  
-MSM075, and -MSMC110

Dear Mr. Jason Moulton:

NOTICE OF AUTHORIZATION TO APPLY THE UL MARK

We have completed our engineering investigation under project number 98SC2224 and find the products comply with the applicable requirements.

This fax temporarily supplements the UL Follow-Up Services Inspection Procedure and serves as authorization to apply the UL Recognized Marking and/or Recognized Component Mark to the above products which are constructed as described below:

Identical to new models, which were submitted to UL for this investigation. The UL records covering the product will be in the Follow-Up Services Inspection Procedure, File E174545, Vol. 1.

To provide the manufacturer with the intended authorization to use the UL Mark, the addressee must send a copy of this Notice and all attached material to each manufacturing location.

This authorization is effective for 90 days only from the date of this Notice. Records covering the products are now being prepared and will be sent to you in the near future.

Products which bear the UL Mark shall be identical to those which were evaluated by UL and found to comply with UL's requirements.

E174545  
March 20, 1998  
Page 2

If changes in construction are discovered, the authorization to use the UL Mark may be withdrawn and products that bear the UL Mark may have to be revised (in the field or at the manufacturer's facility) to bring them into compliance with UL's requirements.

Regards,

ALAN PORDES (Ext. 32443)  
Engineering Group Leader  
Engineering Services  
Section 316K  
Email: pordesa@ul.com

Reviewed by:

JOEL HAWK (Ext. 32188)  
Project Engineer  
Engineering Services  
Section 316K