BOURNS

Product Obsolescence Memo

INDUCTIVE COMPONENTS



October 30, 2018

Bourns® Model 74F686AP-3%-RC and 74F686AP-3%-TR-RC Axial Lead Inductors to be Discontinued

Bourns® Model 74F686AP-3%-RC and 74F686AP-3%-TR-RC Axial Lead Inductors will be discontinued. A lack of sales volume and diminishing demand necessitates this action. Regrettably, no replacement part numbers are available.

Obsolete Part Numbers:

74F686AP-3%-RC

74F686AP-3%-TR-RC

Please plan for the following deadlines: Last time buy date: **February 28, 2019** Last time ship date: **May 31, 2019**

If you have any questions or need additional information, please feel free to contact <u>Customer Service/</u> Inside Sales.

IC1865

 Americas:
 Tel: +1-951 781-5500
 EMEA:
 Tel: +36 88 520 390
 Asia-Pacific:
 Tel: +886-2 2562-4117

 americus@bourns.com
 eurocus@bourns.com
 asiacus@bourns.com