



March 31, 2003

Bourns Rep District Sales Managers
Bourns Rep Distributor Managers
Corporate Distributor Product Managers
Americas Sales Team
Asia Sales Team
Europe Sales Team



Bourns® Multifuse® MF-SM/33 Marking Change

Effective immediately, part marking and date coding on all Bourns® Multifuse® MF-SM/33 Series part numbers is being changed. The change provides marking consistency with other Multifuse® surface mount families. Packaging labels will not change.

<u>Parts Affected</u>	<u>Old Part Marking</u>	<u>New Part Marking</u>
MF-SM100/33-2	3100 B3A	100 B3A
MF-SM150/33-2	3150 B3A	150 B3A

If you have questions please contact your local Bourns sales contact or Multifuse® product management.