



PRODUCT CHANGE NOTIFICATION

TRIMPOT® TRIMMING POTENTIOMETERS



Bourns® Model 3339 Series Trimpot® Trimming Potentiometers

Part Marking Lettering Update

Riverside, California – June 15, 2022 – Effective July 1st, 2022, Bourns will update the part marking lettering on the [Model 3339 Trimpot® Trimming Potentiometer](#). This change will simplify the lettering on the actual part, making it easier to read the markings on the product.

A list of affected models is included on page 2. The change in part marking lettering will not affect the form, fit, function, reliability or quality of the Trimpot® Trimming Potentiometer. The product specifications will not change. This is being done as a convenience for our customers for easier recognition of the Bourns product.

Current Lettering



New Lettering



If you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).

Users should verify that the described changes will not impact the performance of the product in their specific applications.

T2208

Affected Part Numbers

| | | | |
|---------------|---------------|---------------|---------------|
| 3339H-1-100 | 3339P-1-101LF | 3339P-1-501 | 3339S-1-503LF |
| 3339H-1-100LF | 3339P-1-102 | 3339P-1-501LF | 3339W-1-100 |
| 3339H-1-101 | 3339P-1-102LF | 3339P-1-502LF | 3339W-1-100LF |
| 3339H-1-101LF | 3339P-1-103 | 3339P-1-503 | 3339W-1-101 |
| 3339H-1-102 | 3339P-1-103LF | 3339P-1-503LF | 3339W-1-101LF |
| 3339H-1-102LF | 3339P-1-104 | 3339P-1-504 | 3339W-1-102 |
| 3339H-1-103 | 3339P-1-104LF | 3339P-1-504LF | 3339W-1-102LF |
| 3339H-1-103LF | 3339P-1-105 | 3339S-1-101 | 3339W-1-103 |
| 3339H-1-104 | 3339P-1-105LF | 3339S-1-101LF | 3339W-1-103LF |
| 3339H-1-104LF | 3339P-1-200 | 3339S-1-102 | 3339W-1-104 |
| 3339H-1-105 | 3339P-1-200LF | 3339S-1-102LF | 3339W-1-104LF |
| 3339H-1-105LF | 3339P-1-201 | 3339S-1-103 | 3339W-1-105 |
| 3339H-1-200 | 3339P-1-201LF | 3339S-1-103LF | 3339W-1-105LF |
| 3339H-1-200LF | 3339P-1-202 | 3339S-1-104 | 3339W-1-200 |
| 3339H-1-201 | 3339P-1-202LF | 3339S-1-104LF | 3339W-1-200LF |
| 3339H-1-201LF | 3339P-1-203 | 3339S-1-200 | 3339W-1-201 |
| 3339H-1-202 | 3339P-1-203LF | 3339S-1-200LF | 3339W-1-201LF |
| 3339H-1-202LF | 3339P-1-204 | 3339S-1-201 | 3339W-1-202 |
| 3339H-1-203 | 3339P-1-204LF | 3339S-1-201LF | 3339W-1-202LF |
| 3339H-1-203LF | 3339P-1-222 | 3339S-1-202 | 3339W-1-203 |
| 3339H-1-204 | 3339P-1-222LF | 3339S-1-202LF | 3339W-1-203LF |
| 3339H-1-204LF | 3339P-1-223 | 3339S-1-203 | 3339W-1-204 |
| 3339H-1-253 | 3339P-1-223LF | 3339S-1-203LF | 3339W-1-204LF |
| 3339H-1-253LF | 3339P-1-224 | 3339S-1-204 | 3339W-1-253 |
| 3339H-1-500 | 3339P-1-252 | 3339S-1-204LF | 3339W-1-253LF |
| 3339H-1-500LF | 3339P-1-252LF | 3339S-1-253 | 3339W-1-500 |
| 3339H-1-501 | 3339P-1-253 | 3339S-1-253LF | 3339W-1-500LF |
| 3339H-1-501LF | 3339P-1-253LF | 3339S-1-254 | 3339W-1-501 |
| 3339H-1-502 | 3339P-1-254 | 3339S-1-254LF | 3339W-1-501LF |
| 3339H-1-502LF | 3339P-1-254LF | 3339S-1-500 | 3339W-1-502 |
| 3339H-1-503 | 3339P-1-472 | 3339S-1-500LF | 3339W-1-502LF |
| 3339H-1-503LF | 3339P-1-472LF | 3339S-1-501 | 3339W-1-503 |
| 3339H-1-504 | 3339P-1-474 | 3339S-1-501LF | 3339W-1-503LF |
| 3339H-1-504LF | 3339P-1-474LF | 3339S-1-502 | 3339W-1-504 |
| 3339P-1-100 | 3339P-1-500 | 3339S-1-502LF | 3339W-1-504LF |
| 3339P-1-100LF | 3339P-1-500LF | 3339S-1-503 | |