

Product Change Notification

CHIP INDUCTORS

Bourns Manufacturers Representatives Corporate Distributor Product Managers Americas Sales Team Asia Sales Team Europe Sales Team Bourns Internal Bourns Plant Managers



November, 2009

Chip Inductor Model CM100505 Carrier Tape Change

Effective January 1, 2010, the carrier tape of model CM100505 will be changed slightly. The bottom hole at the center of the pocket will be sealed. Test results have shown no difference in inductor pick up from a carrier tape with a sealed bottom hole pocket.

