



# PRODUCT OBSOLESCENCE MEMO

## MAGNETICS

### Bourns® 1860xx Series Transponder Coils to be Discontinued

*Riverside, California* – May 23, 2025 - In accordance with our ongoing product life cycle management procedure, effective immediately, Bourns will transfer the 1860xx Series Transponder Coils to an End of Product Life status. A lack of sales volume and diminishing demand necessitates this action. A list of obsolete part numbers is included below.

| Obsolete Part Numbers |
|-----------------------|
| 186016-000            |
| 186017-000            |
| 186038-000            |
| 186039-001            |
| 186024-000            |
| 186042-000            |

Regrettably, no replacement part numbers are available at this time.

*If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).*

IC25042