



PRODUCT OBSOLESCENCE MEMO

MAGNETICS

Bourns® Model 08556 and RLF1507 Inductors to be Discontinued

Riverside, California — April 30, 2025 — In accordance with our ongoing product life cycle management procedure, effective immediately, Bourns will transfer the Model 08556 and RLF1507 Inductors to an End of Product Life status. A lack of sales volume and diminishing demand necessitates this action. A list of obsolete part numbers is included below.

Obsolete Part Numbers
08556-RC
RLF1507-300Y

Regrettably, no replacement part numbers are available at this time.

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

IC25074