



# PRODUCT OBSOLESCENCE MEMO

## MAGNETICS

### Bourns Kaschke Ferrites to be Discontinued

REVISED JUNE 17, 2025

Riverside, California – May 29, 2025 – In accordance with our ongoing product life cycle management procedure and the reorganization of our Göttingen facility, effective May 30, 2025, Bourns will transfer all Kaschke Ferrites to an End of Life status. The restructure of our Göttingen facility necessitates this action. A list of obsolete part numbers is included below.

#### Obsolete Part Numbers

|              |              |              |              |               |               |               |
|--------------|--------------|--------------|--------------|---------------|---------------|---------------|
| 205014600010 | 304020100250 | 317063825026 | 317362315006 | 320120409028  | 336090300025  | 347191337024  |
| 205014700010 | 304040300250 | 317080001028 | 317362315026 | 320120615026  | 336094400024  | 347241400026  |
| 250250019000 | 304050300040 | 317090406024 | 317362315055 | 320150400026  | 336130700025  | 347241480026T |
| 250250021000 | 304060250250 | 317100604004 | 317362315250 | 320200630028  | 336134500025  | 349320945026A |
| 301030250024 | 304060280041 | 317100604006 | 317402416004 | 320250700004  | 336140426713  | 370062080004  |
| 301060290040 | 304080250041 | 317100604026 | 317402416006 | 320301100026  | 336144500024  | 381262820024A |
| 301060500040 | 304080300024 | 317100604100 | 317402416028 | 320320900026  | 336144500025  | 381262820028A |
| 301080200041 | 304080300041 | 317102001007 | 317402416055 | 320320925028  | 336144700024  | 381303625224T |
| 301080260041 | 304080300250 | 317138363004 | 317402520006 | 320422000028  | 336180500025  | 381932820024  |
| 301080300040 | 304080400250 | 317140905004 | 317503020006 | 320552175026  | 336220600024  | 381932830028  |
| 301100380250 | 304080500024 | 317140905055 | 317503020026 | 325002500024  | 336220600025  | 382121900028  |
| 301100500040 | 304100500041 | 317140906004 | 317563218004 | 325002500026  | 336250900024  | 382121900028Z |
| 301100600026 | 306083116026 | 317140906026 | 317563218006 | 325100300026  | 336258600024  | 382182090801  |
| 302030561024 | 306105060024 | 317140909004 | 317563218007 | 325100305224  | 336300900024  | 382184001028  |
| 302050461026 | 306106018080 | 317201010006 | 317563218026 | 325173501026  | 336300900025  | 382184001800  |
| 302080601026 | 306412044024 | 317201010026 | 317584017004 | 325200700024  | 336351129025  | 382184001801  |
| 302080602600 | 306603018024 | 317201074006 | 317584017026 | 325241000024  | 336361130024  | 382221901221  |
| 302100701250 | 311351230250 | 317201074100 | 317633825006 | 325340700024  | 336701214004  | 382221901221Z |
| 302100801026 | 311351650251 | 317211096026 | 317633825028 | 325462800024  | 336701414024  | 382222590028  |
| 302100911026 | 311402038014 | 317231407006 | 317633825055 | 325821500040  | 336701414025  | 382226010028  |
| 302101001026 | 312052023250 | 317231407055 | 317804015004 | 325935600028  | 336701499025  | 391012001026  |
| 302101001250 | 312052255800 | 317251510004 | 317804015006 | 325937600024  | 336821615004  | 391013001026  |
| 302101001600 | 312069001800 | 317251510006 | 317804015026 | 325937600028  | 340008830224  | 391015001026  |
| 302101201026 | 312073023250 | 317251510024 | 317804020026 | 325951600800  | 340040001224T | 391063204026  |
| 302101401024 | 312073023800 | 317251510026 | 318026615004 | 326140000026  | 340100001224  | 391073205026  |
| 302101401026 | 312073033250 | 317251510055 | 318100603800 | 326220000026A | 340109640024  | 391083209026  |
| 302101401250 | 312073043250 | 317261420004 | 318100604052 | 326300000004  | 340202037040  | 391084209026  |
| 302101402026 | 312074043800 | 317281819004 | 318191115004 | 326360000028  | 340262620040  | 391093206026  |
| 302101501600 | 312362253004 | 317281819006 | 318201111004 | 328083403713  | 340262625040  | 391103206026  |
| 302151001024 | 312362253800 | 317291915028 | 318251510004 | 328093110026  | 340595330040  | 391105206026  |
| 302152451024 | 313905810800 | 317311912004 | 318251510006 | 328093904713  | 340786140040  | 391113208026  |
| 303351814600 | 317026615004 | 317311912006 | 318261420250 | 328136005713  | 340926630040  | 391115208026  |
| 303351815250 | 317026615006 | 317311912026 | 318291915055 | 335133151713  | 340936730040  | 391123208026  |
| 303351819600 | 317026615028 | 317311924026 | 318311912004 | 335249301713  | 343201020026  | 391124208026  |
| 303351825250 | 317026625004 | 317342012024 | 318362315250 | 336060313004  | 345372600024  | 391125208026  |
| 303351880250 | 317063825004 | 317342012055 | 320100300004 | 336070401026  | 346472409024  | 391126208026  |
| 303501811024 | 317063825006 | 317362315004 | 320100320026 | 336090300024  | 347191300024  | 391135208026  |

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

IC25098REV

### Obsolete Part Numbers

|               |               |               |              |               |              |               |
|---------------|---------------|---------------|--------------|---------------|--------------|---------------|
| 391137208026  | 391271208026  | 391736208026Z | 402080653024 | 402192004026  | 418261420250 | 635000001958  |
| 391144208026  | 391273208026E | 391800208026  | 402081504026 | 402201504026  | 418362320250 | 6352584000003 |
| 391145208026  | 391278208026E | 391800208026Z | 402082001026 | 402202003026  | 418362322004 | 695244600000  |
| 391146208026  | 391283208026E | 391958208026  | 402082003026 | 402202004026  | 418553115024 | 749171006605  |
| 391147208026  | 391284208026E | 391958208026Z | 402082004026 | 402212004026  | 425262000028 | 749171028654  |
| 391154208026  | 391290208026E | 398581730004  | 402091504026 | 402222004026  | 425262800024 | 781303625224  |
| 391155208026  | 391294208026E | 398631025006  | 402092003026 | 402232004026E | 425302500024 | 782182090801  |
| 391156208026  | 391305208026E | 399020801026  | 402092004026 | 402242004026E | 500120410627 | 782184001801  |
| 391157208026  | 391323208026E | 399095001800  | 402100631250 | 402252004026E | 500201110117 | 789251300026  |
| 391158208026  | 391326208026E | 399252001028A | 402100641026 | 402272004026E | 500210720027 | 789251300028  |
| 391165208026  | 391330208026E | 399263601024  | 402100671026 | 402302004026E | 501160210917 | 817875430008  |
| 391166208026  | 391335208026  | 399317125006  | 402100981026 | 402332009026E | 502120420427 | 820120400028  |
| 391168208026  | 391340208026  | 399319067800  | 402101504026 | 404016195024  | 502200710327 | 820120600026  |
| 391169208026  | 391347208026E | 399440203028T | 402101604026 | 404019150006  | 502250720117 | 820160500028  |
| 391176208026  | 391368208026E | 399446301006  | 402101941250 | 404019250006Z | 506200610117 | 820201100028  |
| 391178208026  | 391389208026  | 399811401024  | 402102001026 | 404020120024  | 506200612027 | 820250700028  |
| 391185208026  | 391389208026Z | 402010001026  | 402102001250 | 404021190006  | 507259710127 | 820251100026  |
| 391186208026  | 391402208026  | 402013001026  | 402102003026 | 404075280024  | 507259712127 | 820320900028  |
| 391188208026  | 391402208026Z | 402017001026  | 402102004026 | 404080183026  | 507259712627 | 820652700028  |
| 391189208026  | 391421208026  | 402018001026  | 402111504026 | 404919190006Z | 507259720827 | 825120002028A |
| 391196208026  | 391421208026Z | 402022002024  | 402112003026 | 407063200026  | 507259722527 | 829146152250  |
| 391198208026  | 391442208026  | 402030371024  | 402112004026 | 407084200026  | 546211710017 | 836022001024  |
| 391199208026E | 391442208026Z | 402031504026  | 402120701026 | 407094200026  | 546250171685 | 836022001025  |
| 391200208026  | 391443208026  | 402032003026  | 402121504026 | 407105200026  | 546250171687 | 836591899024  |
| 391206208026  | 391443208026Z | 402032004026  | 402122001026 | 407126200026  | 560151600798 | 845157800028  |
| 391210208026  | 391463208026  | 402040641024  | 402122003026 | 407147200026  | 560151612798 | 909025990053  |
| 391211208026  | 391463208026Z | 402041504026  | 402122004026 | 407157200026  | 603291812007 |               |
| 391216208026  | 391482208026  | 402042001026  | 402132003026 | 407168200026  | 615171171708 |               |
| 391221208026  | 391482208026Z | 402042003026  | 402132004026 | 407189200026  | 615171271986 |               |
| 391226208026  | 391484208026  | 402042004026  | 402142003026 | 408402080024  | 615199800007 |               |
| 391231208026E | 391484208026Z | 402051504026  | 402142004026 | 409402011024  | 616140171517 |               |
| 391233208026  | 391542208026  | 402052003026  | 402151004026 | 409623011006  | 616170171547 |               |
| 391236208026E | 391542208026Z | 402052004026  | 402151504026 | 410100813024  | 616180170053 |               |
| 391240208026  | 391557208026  | 402060801026  | 402152003026 | 410100824024  | 616180171427 |               |
| 391242208026E | 391557208026Z | 402061504026  | 402152004026 | 410251230024  | 616270171428 |               |
| 391246208026E | 391603208026  | 402062003026  | 402162003026 | 412472923004  | 616320171180 |               |
| 391250208026E | 391603208026Z | 402062004026  | 402162004026 | 417160906006  | 616320171200 |               |
| 391252208026E | 391652208026  | 402072003026  | 402172004026 | 417311912006  | 616320271180 |               |
| 391256208026E | 391652208026Z | 402072004026  | 402182003026 | 418140901004  | 616430171181 |               |
| 391263208026E | 391736208026  | 402080463026  | 402182004026 | 418261415250  | 616430371181 |               |

Regrettably, no replacement part numbers are available at this time. Customers may continue to purchase these part numbers during the End of Product Life transition period between now and May 30, 2025. Orders for these part numbers during this End of Product Life transition period will be considered noncancellable. Products purchased during this End of Product Life transition period will be considered nonreturnable and will be covered by Bourns' standard warranty.

#### Please plan for the following deadlines:

Last time buy date: **May 30, 2025**

Last time ship date: **December 31, 2025**

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).