



PRODUCT OBSOLESCENCE MEMO

MAGNETICS

Bourns® 111596-000, 111597-000, 111841-000 and 189382-002 Inductor Coils to be Discontinued

Riverside, California – July 16, 2025 – In accordance with our ongoing product life cycle management procedure, July 30, 2025, Bourns will transfer the 111596-000, 111597-000, 111841-000 and 189382-002 Inductor Coils to an End of Product Life status. A lack of sales volume and diminishing demand necessitates this action. A list of obsolete part numbers is included below.

Obsolete Part Numbers
111596-000
111597-000
111841-000
189382-002

Regrettably, no replacement part numbers are available at this time. If there is a need for a replacement part in the future, Bourns is ready to collaborate with customers to develop a new design.

Please plan for the following deadlines:

Last time buy date: **July 30, 2025**

Last ship date: **December 31, 2025**

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

IC25127