

Product Obsolescence Memo

TBU® HIGH-SPEED PROTECTORS

June, 2014

Bourns® Model TBU-PK Series TBU® High-Speed Protectors to be Discontinued

In accordance with our ongoing product lifecycle management procedure, Bourns has identified select TBU® High-Speed Protector products that will be transferred to an End of Product Life status. A lack of sales volume and diminishing demand necessitates this action.

The suggested replacement part numbers are listed below. Please contact the Bourns team of Field Application Engineers if you have any questions regarding the suggested replacement parts and your application requirements.

Products purchased during this End of Product Life transition period will be covered by Bourns' standard warranty. Last Time Buy orders for the discontinued products will be considered non-cancellable and non-returnable.

Obsolete Part Numbers	Replacement Part Numbers
TBU-PK050-100-WH	TBU-PL050-100-WH
TBU-PK060-100-WH	TBU-PL060-100-WH
TBU-PK075-100-WH	TBU-PL075-100-WH
TBU-PK085-100-WH	TBU-PL085-100-WH

Please plan for the following deadlines:

Last time buy date: April 30, 2015

Last time ship date: June 30, 2015

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).