

Product Obsolescence Memo

CURRENT SENSE RESISTORS

February, 2018

Bourns® Model FR-SAB-0-001 Current Sense Resistor Sample Board to be Discontinued

Effectively immediately, Bourns has discontinued the Model FR-SAB-0-001 Current Sense Resistor Sample Board. Diminishing demand necessitates this action. The suggested replacement sample board, Model FR-SAB-0-002 has been updated with new products.

Obsolete Sample Board FR-SAB-0-001		Suggested Replacement Sample Board FR-SAB-0-002	
Model	Chip Size	Model	Chip Size
CRL0603	0603	CRL0603	0603
CRL0805	0805	CRL0805	0805
CRL1206	1206	CRL1206	1206
CRL2010	2010	CRL2010	2010
CRL2512	2512	CRL2512	2512
CRF0805	0805	CRM0603(A)	0603
CRF1206	1206	CRM0805(A)	0805
CRF2512	2512	CRM1206(A)	1206
CRF2512	2512	CRM2010(A)	2010
CRE2512	2512	CRM2512(A)	2512
CRA2512	2512	CRF0805	0805
CST0612	0612	CRF1206	1206
CSS2H-2512	2512	CRF2512	2512
CSS2H-3920	3920	CRF2512	2512
CSS2H-5930	5930	CRE2512	2512
CSS4J-4026	4026	CRA2512	2512
		CST0612	0612
		CSS2H-2512	2512
		CSS2H-3920	3920
		CSS2H-5930	5930
CSS4J-4026	4026		

Please visit the Bourns website at www.bourns.com for specific product details. If you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).