




# Product Obsolescence Memo

Bourns Manufacturers Representatives  
Corporate Distributor Product Managers  
Americas Sales Team  
Asia Sales Team  
Europe Sales Team



## CD1206-S0180 & CD1206-S0180R Diodes End of Life

Riverside, California - April 18, 2007 - Bourns successfully provided High Speed Switching Diodes for four years. Unfortunately, due to inadequate sampling requests and production orders Bourns will discontinue two specific models within this family: CD1206-S0180 and CD1206-S0180R.

Replacement part numbers are listed below:

Discontinued P/N

CD1206-S0180  
CD1206-S0180R

Replacement P/Ns

CD1206-S01575 or CD1005-S0180  
CD1206-S01575 or CD1005-S0180R

The last time buy date is April 27, 2007 with a last time shipment date of June 29, 2007. Datasheets for the replacement part numbers are available on [www.bourns.com](http://www.bourns.com).

E0707

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_