

Product Change Notification

INDUCTIVE COMPONENTS

August, 2017

Bourns® Model 7500 Series Common Mode Chokes *Change to Manufacturing Process*

Bourns is making a change to the manufacturing process of the [Model 7500 Series Common Mode Chokes](#).

In the current coating process, the core / winding assembly is dipped in a varnish bath.

The revised process will apply the coating material to the winding only. The revised process may improve inductance.

The common mode chokes' form (appearance) will change because the core will not be varnished. There will be no change to the fit or function of the chokes. The quality and reliability of the common mode chokes should be enhanced.

Affected Part Numbers

7502-RC	7512-RC
7504-RC	7514-RC
7506-RC	7516-RC
7508-RC	7518-RC
7510-RC	

Implementation dates are as follows:

Date that manufacturing of existing products will cease: November 30, 2017

Date that deliveries of modified products will begin: December 1, 2017

First date code using the above changes: 1748

If you have any questions or need additional information, please feel free to contact [Customer Service/ Inside Sales](#).