

## Product Change Notification

TRIMPOT® TRIMMING POTENTIOMETERS




May, 2016

### Bourns® Model 3329P-DK9, PV32P, RJ50, and RJR50 Round Trimming Potentiometers *Change to Packaging Tube*

Bourns is pleased to announce an upgrade to the packaging tubes for the [Model 3329P-DK9](#), [PV32P](#), [RJ50](#) and [RJR50](#) Round Trimming Potentiometers. The new packaging tube will be shaped much like the trimmer itself, rather than the less efficient shape that is currently being used.

There are no changes to the form, fit, function, quality or reliability of the trimmers themselves. The packaging tube's fit (physical dimensions) and form (the appearance, such as the shape) will be changed. A list of the affected part numbers is shown in Table 1 on the next page.



*Current Packaging Tube*

*New Packaging Tube*

Implementation dates are as follows:

*Date that manufacturing of existing product packaging will cease: July 26, 2016*

*Date that deliveries of modified product packaging will begin: July 27, 2016*

*First date code using above changes: 1631C*

If you have any questions or need additional information, please feel free to contact [Customer Service/ Inside Sales](#).

**TABLE 1**

3329P-DK9	PV32P	RJ50	RJR50
3329P-DK9-100	PV32P100A01B00	RJ50CP101	RJR50FP100M
3329P-DK9-101	PV32P101A01B00	RJ50CP102	RJR50FP100P
3329P-DK9-102	PV32P102A01B00	RJ50CP103	RJR50FP101M
3329P-DK9-103	PV32P103A01B00	RJ50CP105	RJR50FP101P
3329P-DK9-104	PV32P104A01B00	RJ50CP200	RJR50FP102M
3329P-DK9-200	PV32P105A01B00	RJ50CP202	RJR50FP102P
3329P-DK9-201	PV32P200A01B00	RJ50CP203	RJR50FP103M
3329P-DK9-201	PV32P201A01B00	RJ50CP500	RJR50FP103P
3329P-DK9-202	PV32P202A01B00	RJ50CP501	RJR50FP104M
3329P-DK9-203	PV32P203A01B00	RJ50CP502	RJR50FP104P
3329P-DK9-204	PV32P204A01B00	RJ50CP504	RJR50FP105P
3329P-DK9-500	PV32P205A01B00	RJ50FP100	RJR50FP200M
3329P-DK9-501	PV32P253A01B00	RJ50FP101	RJR50FP200P
3329P-DK9-502	PV32P254A01B00	RJ50FP102	RJR50FP201M
3329P-DK9-503	PV32P500A01B00	RJ50FP103	RJR50FP201P
3329P-DK9-504	PV32P501A01B00	RJ50FP104	RJR50FP202M
3329P-DK9-100LF	PV32P502A01B00	RJ50FP105	RJR50FP202P
3329P-DK9-101LF	PV32P503A01B00	RJ50FP200	RJR50FP203M
3329P-DK9-102LF	PV32P504A01B00	RJ50FP201	RJR50FP203P
3329P-DK9-103LF	PV32P505A01B00	RJ50FP202	RJR50FP204P
3329P-DK9-104LF		RJ50FP203	RJR50FP253P
3329P-DK9-105LF		RJ50FP204	RJR50FP254P
3329P-DK9-201LF		RJ50FP253	RJR50FP500P
3329P-DK9-203LF		RJ50FP254	RJR50FP501P
3329P-DK9-204LF		RJ50FP500	RJR50FP501PQ
3329P-DK9-253		RJ50FP501	RJR50FP502M
3329P-DK9-254		RJ50FP502	RJR50FP502MQ
3329P-DK9-500LF		RJ50FP503	RJR50FP502P
3329P-DK9-501LF		RJ50FP504	RJR50FP503M
3329P-DK9-502LF			RJR50FP503P
3329P-DK9-504LF			RJR50FP504P