

Product Obsolescence Memo

W A F E R S

December 20, 2018

Bourns® Model SDxxx, HPxxx and FLxxx to be Discontinued

In accordance with our ongoing product lifecycle management procedure, Bourns has identified select SDxxx, HPxxx and FLxxx Models that have been transferred to an End of Product Life status. A lack of sales volume and diminishing demand necessitates this action.

Obsolete Part Numbers			
SD107VQ	SD135VQ	SD634VQ	FL205VQ
SD110VQ	SD140BQ	SD635VQ	HP180EQ
SD115VQ	SD145VQ	SD636VQ	
SD125VQ	SD632VQ	SD636VZ	

Regrettably, suggested replacement products are not available at this time. Customers must notify Bourns in writing within 30 days of receipt of this notification if they consider the discontinued product to be "sole sourced" by Bourns. In such cases, Bourns will work with customers to negotiate an appropriate end-of-life purchase for the discontinued products. Products purchased during this End of Product Life transition period will be covered by Bourns' standard warranty. Last Time Buy orders for these products will be considered non-cancellable and non-returnable.

Please plan for the following deadlines:

Last Time Buy Date: June 30, 2019

Last Time Ship Date: December 31, 2019

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).

ESD1854