



Resistive Products Division **Bourns Electronics Taiwan Ltd.**

No 1, Kung 6th Road, Industrial Zone II
Lin-Kou, Taipei
Taiwan R.O.C.

Trimpot RoHS Test Report






MODEL: 7914



By Quality Assurance Department

Ref No: 07-006

MATERIAL DECLARATION SHEET

No.	Construction Element	Material Group	Report No.	Note
1	Housing/ Adaptor	Thermoplastic	 D:\RoHS Report\ 2007\CE_2006_B104	A
2	Actuation Dome	Stainless Steel	 D:\RoHS Report\ 2007\CE_2006_B112	A
3	PAD	Rubber	 D:\RoHS Report\ 2007\CE_2006_B104	A
4	LID	Stainless Steel	 D:\RoHS Report\ 2007\CE_2006_B112	A
5	Lead Frame/ Terminals	Brass with Gold plating	 D:\RoHS Report\ 2007\CE_2006_B112	A

- Note A: RoHS compliance.

Requirement:

- ❖ Contain Pb 、 Hg 、 Cr+6 、 PBB and PBDE < 0.1 % (1000 ppm) by weight.
- ❖ Contain Cd < 0.01 % (100 ppm) by weight