

## PRODUCT CHANGE NOTIFICATION TBU® HIGH-SPEED PROTECTORS

•



## **Additional Assembly Site for Model TBU-DF Series TBU® High-Speed Protectors**

Riverside, California – July 16, 2019 – The Bourns® Model TBU-DF TBU® High-Speed Protector Series will now be assembled at an additional site to help support the increasing demand for these devices.

Currently, these devices are assembled in Laguna, Philippines. The addition of an assembly site in Shanghai, China will help provide a secure, flexible supply chain to our customers. This new assembly site in Shanghai, China is an existing assembly site for other Bourns® TBU® High-Speed Protector Series.

Assembly at the additional site does not impact the form, fit, or function or the reliability or quality of the products. The qualification test data and evaluation samples are now available.

The affected part numbers are listed in the table below.

| Affected Part Numbers   |                         |
|-------------------------|-------------------------|
| <u>TBU-DF055-050-WH</u> | TBU-DF085-300-WH        |
| <u>TBU-DF055-300-WH</u> | <u>TBU-DF055-500-WH</u> |
| TBU-DF085-050-WH        | TBU-DF085-500-WH        |

Implementation dates are as follows:

First date code using the above changes: 931

Date that deliveries of products from the additional location will begin: October 1, 2019

If you have any questions or need additional information, please feel free to contact <u>Customer Service/Inside Sales</u>.

FU1905