




# PRODUCT CHANGE NOTIFICATION

## MAGNETICS



### Bourns® Model SRR1050A, SRR1050HA, SRR1040, SRR8030, and SRR8045 Series Shielded Power Inductors

#### *Relocation of Manufacturing Plant*

Riverside California – April 28, 2023 – Effective May 20, 2023, manufacturing of the [Model SRR1050A](#), [SRR1050HA](#), SRR1040, SRR8030, and SRR8045 Series Shielded Power Inductors will be relocated to a higher capacity manufacturing facility to accommodate increased production demands.

There will be no product design, material or manufacturing process changes as a result of the manufacturing plant relocation.

The form, fit, function, quality, reliability and country of origin of these inductors will not change. The production lead time of these inductors remains the same. Traceability will be maintained through lot code and date code.

A list of affected part numbers is included below.

Affected Part Numbers					
SRR1050A-100Y	SRR1050A-2R2Y	SRR1050A-180YG	SRR1050HA-271Y	SRR1050HA-8R2Y	SRR1040-270Y
SRR1050A-101Y	SRR1050A-330Y	SRR1050HA-100Y	SRR1050HA-2R2Y	SRR1050HA-R68Y	SRR1040-271Y
SRR1050A-120Y	SRR1050A-331Y	SRR1050HA-101Y	SRR1050HA-330Y	SRR8030-100YA	SRR1040-330Y
SRR1050A-121Y	SRR1050A-390Y	SRR1050HA-120Y	SRR1050HA-331Y	SRR1040-100Y	SRR1040-331Y
SRR1050A-150Y	SRR1050A-3R3Y	SRR1050HA-121Y	SRR1050HA-390Y	SRR1040-101Y	SRR1040-390Y
SRR1050A-151Y	SRR1050A-470Y	SRR1050HA-150Y	SRR1050HA-3R3Y	SRR1040-120Y	SRR1040-3R3Y
SRR1050A-180Y	SRR1050A-4R2Y	SRR1050HA-151Y	SRR1050HA-470Y	SRR1040-121Y	SRR1040-470Y
SRR1050A-181Y	SRR1050A-560Y	SRR1050HA-180Y	SRR1050HA-471Y	SRR1040-150Y	SRR1040-560Y
SRR1050A-1R2Y	SRR1050A-680Y	SRR1050HA-181Y	SRR1050HA-4R2Y	SRR1040-151Y	SRR1040-5R6Y
SRR1050A-220Y	SRR1050A-6R8Y	SRR1050HA-1R2Y	SRR1050HA-560Y	SRR1040-180Y	SRR1040-680Y
SRR1050A-221Y	SRR1050A-820Y	SRR1050HA-220Y	SRR1050HA-680Y	SRR1040-181Y	SRR1040-820Y
SRR1050A-270Y	SRR1050A-8R2Y	SRR1050HA-221Y	SRR1050HA-6R8Y	SRR1040-220Y	SRR8045-822M
SRR1050A-271Y	SRR1050A-R68Y	SRR1050HA-270Y	SRR1050HA-820Y	SRR1040-221Y	

Samples built at the new manufacturing site are available upon request. Bourns recommends that customers test the affected part number(s) in their specific applications for verification of satisfactory performance.

#### Implementation dates are as follows:

First date code for products from the new location: **2320**

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

Users should verify that the described changes will not impact the performance of the product in their specific applications.

IC22117