


Product Change Notification

HIGH-SPEED PROTECTORS



September, 2016

Bourns® TBU® and TCS™ High-Speed Protectors

- Product Labels Will Now Include Product Series Name -

In the spirit of continuous improvement, production labels for Bourns® TBU® and TCS™ High-Speed Protectors will now include the product series name. The primary reason for making this change is to provide more clarity, as the current 2D barcode format only indicates the part number.

This change is a label change only and will have no effect on the form, fit or function of the Bourns® products themselves. The manufacturing process remains unchanged and agency certifications are unaffected. Bourns will begin phasing in this process on or about November 1, 2016. Goods manufactured prior to implementation of this label change will not contain the series name. A list of the affected part numbers is on the following page.

| Current Label | New Label |
|--|---|
| <p>BOURNS® PN: TBU-CA085-500-WH MADE IN: CHINA QTY: 3000 DC: 50301 QRA LOT: AC11895.02#01 C SOF:T CHIPCO: UK MSL1 Category RoHS</p> | <p>BOURNS® TBU® High-Speed Protectors PN: TBU-CA085-500-WH MADE IN: CHINA QTY: 3000 DC: 50301 QRA LOT: AC11895.02#01 C SOF:T CHIPCO: UK MSL1 Category RoHS</p> |
| <p>BOURNS® PN: TCS-DL004-250-WH MADE IN: CHINA QTY: 3000 DC: 54301 QRA LOT: ADT0149.01#03 C SOF:T CHIPCO: UK MSL1 Category RoHS</p> | <p>BOURNS® TCS™ High-Speed Protectors PN: TCS-DL004-250-WH MADE IN: CHINA QTY: 3000 DC: 54301 QRA LOT: ADT0149.01#03 C SOF:T CHIPCO: UK MSL1 Category RoHS</p> |

Implementation dates are as follows:

Date that deliveries of modified product labels will begin: November 1, 2016

First date code using the above changes: 1644

If you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).

Affected Part Numbers

| | | |
|------------------|------------------|------------------|
| C650-100-WH | TBU-CA050-100-WH | TBU-DT085-500-WH |
| C650-180-WH | TBU-CA050-200-WH | TBU-PL050-100-WH |
| C650-260-WH | TBU-CA050-300-WH | TBU-PL050-200-WH |
| C850-100-WH | TBU-CA050-500-WH | TBU-PL060-100-WH |
| C850-180-WH | TBU-CA065-050-WH | TBU-PL060-200-WH |
| C850-260-WH | TBU-CA065-100-WH | TBU-PL075-100-WH |
| P40-G240-WH | TBU-CA065-200-WH | TBU-PL075-200-WH |
| P750-G120-WH | TBU-CA065-300-WH | TBU-PL085-100-WH |
| P850-G120-WH | TBU-CA065-500-WH | TBU-PL085-200-WH |
| P850-G200-WH | TBU-CA085-050-WH | TCS-DL004-250-WH |
| TBU-CA025-050-WH | TBU-CA085-100-WH | TCS-DL004-500-WH |
| TBU-CA025-100-WH | TBU-CA085-200-WH | TCS-DL004-750-WH |
| TBU-CA025-200-WH | TBU-CA085-300-WH | R3770-TBU |
| TBU-CA025-300-WH | TBU-CA085-500-WH | R3776-TBU |
| TBU-CA025-500-WH | TBU-DT065-100-WH | R3777-TBU |
| TBU-CA040-050-WH | TBU-DT065-200-WH | R3778-TBU |
| TBU-CA040-100-WH | TBU-DT065-300-WH | R3779-TBU |
| TBU-CA040-200-WH | TBU-DT065-500-WH | R3781-TBU |
| TBU-CA040-300-WH | TBU-DT085-100-WH | |
| TBU-CA040-500-WH | TBU-DT085-200-WH | |
| TBU-CA050-050-WH | TBU-DT085-300-WH | |