

PRODUCT OBSOLESCENCE MEMO



Bourns® Model CDT0269-BR1190L and CDT0269-BR1380L Surface Mount Bridge Rectifier Diodes to be Discontinued

Riverside, California – February 25, 2020 – In accordance with our ongoing product lifecycle management procedure, Bourns is discontinuing the Model CDTO269-BR1190L and CDTO269-BR1380L Surface Mount Rectifier Diodes. A lack of sales volume and diminishing demand necessitates this action.

Obsolete Part Numbers
<u>CDT0269-BR1190L</u>
CDT0269-BR1380L

Regrettably, no replacement products are available at this time. Customers must notify Bourns in writing within 30 days of receipt of this notification if they consider the discontinued product to be "sole sourced" by Bourns. In such cases, Bourns will work with customers to negotiate an appropriate end-of-life purchase for the discontinued products. Products purchased during this End of Product Life transition period will be covered by Bourns' standard warranty. Last Time Buy orders for these products will be considered non-cancellable and non-returnable.

Please plan for the following deadlines:

Last time buy date: **November 30, 2020**Last time ship date: **December 31, 2020**

Should you have any questions or need additional information, please feel free to contact <u>Customer Service/Inside Sales</u>.

ESD2002