



# PRODUCT OBSOLESCENCE MEMO

## CO & OUTSIDE PLANT PRODUCTS

### Bourns® Model 50502-01 and 50502-01-CL Power Supply Adapters to be Discontinued

Riverside, California – September 17, 2021 – In accordance with our ongoing lifecycle management procedure, Bourns will transfer the Model 50502-01 and 50502-01-CL Power Supply Adapters to an End of Product life status on October 30, 2021. The limited power supply and lack of CE/RoHS\* compliance and international AC prongs necessitates this action. The discontinued part numbers and their recommended replacement part numbers can be found in the table below.

Affected Part Number	Recommended Replacement Part Number
50502-01	50504-02
50502-01-CL	50504-02-CL

Customers must notify Bourns in writing within 30 days of publication of this notification if they consider the discontinued part numbers to be sole sourced by Bourns. In such cases, Bourns will work with the customer to negotiate an appropriate End of Product Life purchase for the discontinued products. Orders for these discontinued products during this End of Product Life transition period will be considered non-cancellable. Products purchased during this End of Product Life transition period will be considered non-returnable and will be covered by Bourns' standard warranty.

**Please plan for the following deadlines:**

Last time buy date: **October 30, 2021**

Last time ship date: **November 15, 2021**

*If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).*

OSP2104