

September 2005

Bourns Manufacturers Representatives Corporate Distributor Product Managers Americas Sales Team Asia Sales Team Europe Sales Team Bourns Internal Bourns Plant Managers



Product Notification Model TC22 Discontinuation

Bourns[®] Trimpot[®] Product Line is obsoleting Model TC22 due to low market demand. The recommended replacement for the TC22 is the Model 3302. However, please note that the Model 3302 is not available with a rotational stop. No new orders for Model TC22 will be accepted after the release of this product notification.