




# Product Obsolescence Memo

## INDUCTIVE COMPONENTS

Bourns Manufacturers Representatives  
Corporate Distributor Product Managers  
Americas Sales Team  
Asia Sales Team  
Europe Sales Team  
Bourns Internal  
Bourns Plant Managers



March, 2009

### **Model SRP1255 to be Discontinued**

[Model SRP1255](#) will be discontinued on March 31, 2009 due to a lack of volume. Model SRP1250 offers a wider range of values and greater current ratings. [Model SRP1250](#) should be designed into applications that may have been considering Model SRP1255.

A list of part numbers for the SRP1255 series is noted below.

SRP1255-R68M  
SRP1255-1R0M  
SRP1255-1R2M  
SRP1255-2R2M  
SRP1255-3R3M  
SRP1255-4R7M

A last-time buy must be made by March 31, 2009.