

Product Obsolescence Memo

INDUCTIVE COMPONENTS

Bourns Manufacturers Representatives
Corporate Distributor Product Managers
Americas Sales Team
Asia Sales Team
Europe Sales Team
Bourns Internal
Bourns Plant Managers



November, 2011

Model 79F Series Conformal Coated RF Chokes to be Discontinued

Effective July 1, 2012, the Bourns® [Model 79F Series](#) conformal coated RF chokes will be discontinued. This axial leaded RF choke series has experienced very low sales activity for a prolonged period. A lack of sales volume, diminishing demand and a high minimum order quantity for this through-hole inductor series necessitates this action.

The last time buy for the Model 79F Series is June 30, 2012. Orders will be NCNR and may not be scheduled out.

In addition, Bourns will no longer offer samples of the 79F Series.

We regret there is no suitable replacement part for these discontinued RF chokes.

A list of affected part numbers follows:

79F100J-TR-RC	79F180J-TR-RC	79F220K-TR-RC	79F331K-RC	79F471J-TR-RC	79F6R8K-RC	79FR22M-RC
79F100K-RC	79F180K-RC	79F221J-TR-RC	79F331K-TR-RC	79F471K-RC	79F6R8K-TR-RC	79FR22M-TR-RC
79F100K-TR-RC	79F180K-TR-RC	79F221K-RC	79F390J-TR-RC	79F471K-TR-RC	79F820J-TR-RC	79FR27M-RC
79F101J-TR-RC	79F181J-TR-RC	79F221K-TR-RC	79F390K-RC	79F4R7J-TR-RC	79F820K-RC	79FR27M-TR-RC
79F101K-RC	79F181K	79F270J-TR-RC	79F390K-TR-RC	79F4R7K	79F820K-TR-RC	79FR33M-RC
79F101K-TR-RC	79F181K-RC	79F270K-RC	79F391J-TR-RC	79F4R7K-RC	79F8R2J-TR-RC	79FR33M-TR-RC
79F120J-TR-RC	79F181K-TR-RC	79F270K-TR-RC	79F391K-RC	79F4R7K-TR-RC	79F8R2K-RC	79FR39M-RC
79F120K-RC	79F1R0K	79F271J-TR-RC	79F3R3J-TR-RC	79F560J-TR-RC	79F8R2K-TR-RC	79FR39M-TR-RC
79F120K-TR-RC	79F1R0K-RC	79F271K-RC	79F3R3K-RC	79F560K-RC	79FR10M	79FR47M-RC
79F121J-TR-RC	79F1R0K-TR-RC	79F271K-TR-RC	79F3R3K-TR-RC	79F560K-TR-RC	79FR10M-RC	79FR47M-TR-RC
79F121K-RC	79F1R2K-RC	79F2R2K-RC	79F3R9J-TR-RC	79F5R6J-TR-RC	79FR10M-TR-RC	79FR56M-RC
79F121K-TR-RC	79F1R2K-TR-RC	79F2R2K-TR-RC	79F3R9K	79F5R6K-RC	79FR12M-RC	79FR56M-TR-RC
79F150J-TR-RC	79F1R5K-RC	79F2R7K-RC	79F3R9K-RC	79F5R6K-TR-RC	79FR12M-TR-RC	79FR68M-RC
79F150K-RC	79F1R5K-TR-RC	79F2R7K-TR-RC	79F3R9K-TR-RC	79F680J-TR-RC	79FR15M	79FR68M-TR-RC
79F150K-TR-RC	79F1R8K-RC	79F330J-TR-RC	79F470J-TR-RC	79F680K	79FR15M-RC	79FR82M-RC
79F151J-TR-RC	79F1R8K-TR-RC	79F330K-RC	79F470K	79F680K-RC	79FR15M-TR-RC	79FR82M-TR-RC
79F151K-RC	79F220J-TR-RC	79F330K-TR-RC	79F470K-RC	79F680K-TR-RC	79FR18M-RC	
79F151K-TR-RC	79F220K-RC	79F331J-TR-RC	79F470K-TR-RC	79F6R8J-TR-RC	79FR18M-TR-RC	

Please contact your local [Bourns Representative](#) or [Bourns Customer Service](#) for further information.